



Size	25'	Year	1981
Make/Model	Searay		
Power	Twin 470 Mercruiser	Trailer	none
Description	Has canvas, depth/fish finder, & more		
		Asking Price	\$13,995

BOAT **Country**

OVER 150 USED BOATS
IN ONE LOCATION

BRAD HOUG
SALES

1871 Ross Avenue • Everett, WA 98205
(425) 259-6126 • Cell (206) 601-3034 • Fax (425) 252-0345
Toll Free 1-800-697-4252 • www.boatcountry.com
houger2000@yahoo.com



1871 Ross Avenue
 Everett, WA 98205
 1-800-697-4252 or 425-259-6126
 Fax 425-252-0345

WN # _____
 Tri Plate # _____
 Listed By: _____

Used Boat Specifications

Boat Details

Make ~~Sea Ray~~ Searay Model SVR 255
 Year 1981
 Size 25' Dry Weight _____
 Beam size / Max Bridge Clearance 9' 8"
 Max Seating _____ Hull Material Fiberglass
 Cuddy Bow-rider Sun-bridge Command-bridge
 Stove (& or) Oven Sink Refer or Icebox
 Water system _____ Hot water _____ Head Type Manual
 Shower _____ Cabin Heat _____ Generator _____
 FWC _____ Battery system 4 Shorepower _____

Canvas

Engine Details

Engine Make 2 Merc 470 Year Rebuild 06'
 I/O I/B O/B _____ Size / Drive Alpha I
 Engine Hours 880
 Fuel Gasoline Horsepower (total) 170 x 2
 Fuel Capacity 120

Electronics

VHF Radar _____ Loran
 GPS _____ Depth/Fish finder
 AM/FM CD _____ Cassette
 Compass Downrigger 1

Trailer

Make King Saltwater
 Year 2001
 Painted or Galvanized _____

NO TRAILER INCLUDED

Additional Notes and Loose Gear

Cenders lines jackets & floatain
updated upholstery

Asking Price \$ 20,495⁰⁰

BLACK 4 YRS OLD DECENT SHAPE CAMPER CAMPER STORAGE BRIDGE



United Marine
1016 14th St.
Everett, WA 98201

Invoice

Date	Invoice #
9/24/2008	12722

Bill To
Chris Wetmore 16917 237th PL. N.E. Woodinville, WA 98077

Ship To

Quantity	Item Code	Description	Price Each	Amount
1	20001	Rule 4" inline bilge blower	31.59	31.59T
2	20001	180672 elbow gaskets	7.99	15.98T
2	20001	180897 exhaust gaskets	5.49	10.98T
4	20001	11826709113 drive nuts	3.92	15.68T
1	20001	17-45738U rear pin	22.44	22.44T
10	20001	HOS3650386FT 3/8 Fuel hose	3.85	38.50T
2	20001	1086 oil filters	16.13	32.26T
8	20001	406 Spark Plugs	2.99	23.92T
1	20001	Oil sending unit OP24891	55.79	55.79T
41	10001	Labor, Remove bad twin engine Mercruiser model 470's. While the engines were at the machine shop it became apparent the fuel tank had a leak. United Marine removed and reinstalled the fuel tank (8 hours) at no charge to the customer. After the engines were received at Boat Country from the rebuild shop we re-installed the external engine components, re-installed the motors and outdrives, fixed several wiring anomalies and test ran the boat in the river. Both engines performed well. We could not test the engines at full throttle because they need proper break in.	90.00	3,690.00T

Subtotal	\$3,937.14
Sales Tax (8.6%)	\$338.59
Payments/Credits	\$0.00
Balance Due	\$4,275.73